



## TEST CERTIFICATE

Site Number **840-Emirates Auctions** Transaction Date **08 Jun 2023, 16:55:09**  
 Transaction Number **32202268 (CC10006)** Queue Number **737911**



Chassis Number **WDB2400791A001724**  
 Engine Number  
 Vehicle Class **Car**  
 Manufacturer **Mercedes**  
 Model **Maybach 63**  
 Model Year **2007**  
 Color **Silver**  
 Mileage **001 NA**  
 Fuel Type **Petrol**  
 No. Of Cylinders **12**  
 Specification **Imported**

DEFECT	REMARKS	
<b>01 Suspension System</b>		<b>ممتص الصدمات</b>
01.A Shock Absorber	BODY LEVEL LOW	ممتص الصدمات
<b>02 Chassis Condition</b>		<b>الشاسي</b>
02.A Chassis	NOT CHECK	الشاسيه
02.B Chassis Number	VIN NUMBER CHECKED ONLY RIGHT SIDE DOOR STICKER	رقم القاعدة
<b>03 Body</b>		<b>جسم المركبة</b>
03.A Floor	UNDER BODY, FLOORING NOT CHECK	الارضيه
03.B Other	VISUAL TEST ONLY	اخرى
03.C Bonnet	SHOCK WEAK	غطاء المحرك
03.D Vehicle Year Model	2006	سنة صنع المركبة
03.E Paint	PAINT NOT CHECKED ,DENTS SCRATCHES ON BODY,PAINT PORTION FADED, STICKER PORTION DAMAGED	الصبغ
03.F Vehicle Model	57 S	طراز المركبة
03.G Bumper	PORTION DAMAGED, MISALIGN	دعامية
<b>04 Engine Condition</b>		<b>المحرك</b>
04.A Visual Engine Condition	ENGINE NOT START ,ALL SYSTEM NOT CHECKED ,KEY MISSING	حالة المحرك النظري

DEFECT	REMARKS	
04.B Other	ENGINE PARTS MISSING	اخرى
<b>05 Transmission Condition</b>		<b>الجير</b>
05.A Visual Gear Box Condition	NOT CHECK	حالة الجير النظرى
<b>06 Interior Condition</b>		<b>الحالة الداخلية</b>
06.A Other	INTERIOR PORTION DAMAGED	اخرى
06.B Odometer reading	NOT CHECK	قراءة عداد المسافات
<b>07 Tires and Rims Condition</b>		<b>الاطارات</b>
07.A Front Tyre	BOTH SIDE DAMAGED	الاطار الامامي
07.B Rear Tyre	BOTH SIDE DAMAGED	الاطار الخلفي

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.